

GAS SAFETY AND MATERIAL COMPATIBILITY DATA CHART

This data has been compiled from the best information available and is offered as a guide to proper material selection. The data presented are generalized for average conditions of temperature and pressure. The user should always investigate the characteristics of the gas being handled and take all the proper precautions. Our technical staff will be pleased to give free advice and technical information on any gas or chemical product of interest.

	H	HAZARDS FOR HUMANS						Μ	ATER	IALS ()F COI	NSTRI	UCTION
	Tot	JE LAT	nnable	OSIVE		ininum Con	pet Bras	1.0. C. 1.00		Mos Ste	est est	X [®]	
GAS		(X.		í I	/ ¥.	0	v .	('S'	5		*		SPECIAL CHARACTERISTICS
Acetylene		\diamond			R	Ν	R	R	R		R	R	Do not use at pressures exceeding 15psig
Air					R	R	R	R	R	R	R	R	
Ammonia	♦	♦	♦		R	Ν	N	Х	R		R	R	Causes stress cracking of copper and copper alloys
Argon					R	R	R	R	R		R	R	
Arsine*	♦	\$			Х	Ν	Х	Х	R		R	R	Highly toxic, excessive exposure may have delayed effect
Boron Trichloride	♦		♦		Ν	Х	Х	Х	Х	Х	R	R	
Boron Trifluoride	♦		♦		Х	R	R	R	R	R	R	R	
1-3, Butadiene		\$			R	R	R	R	R		R	R	
Butane		♦			R	R	R	R	R		R	R	
Butenes		\$			R	R	R	R	R		R	R	
Carbon Dioxide					R	R	R	R	R		R	R	
Carbon Monoxide	♦	♦			R	R	R	R	R		R	R	
Carbonyl Sulfide	♦	♦			R	Ν	Ν	Х	R		R	R	Treat as Hydrogen Sulfide, affects central nervous system
Chlorine	♦		♦		Ν	Ν	N	Х	Х	Х	R	R	Very toxic and damaging to the respiratory system
Cyanogen*	♦	♦			Х			R	R		R	R	Treat as cyanides
Deuterium		\diamond			R	R	R	R	R		R	R	
Dimethylamine	♦	♦	♦		Х	Ν	N	R	R		Х	R	Attacks copper and copper alloys rapidly.
Dimethyl Ether		♦			R	R	R	R	R		R	R	
Ethane		♦			R	R	R				R	R	
Ethyl Chloride	♦	♦					R	R	R		R	R	
Ethylene		♦			R	R	R	R	R		R	R	
Ethylene Oxide	♦	♦				Ν	Ν	R	R		R	R	Exposure of liquid on skin or clothing can cause dermatitis
Fluorine*	♦		♦		R	R	Х		R	R	Ν	Х	Strong oxidant, can ignite combustible materials and metals
Helium					R	R	R	R	R		R	R	
Hydrogen		♦			R	R	R	R	R		R	R	
Hydrogen Bromide	\$		\diamond		Ν	Х	Ν	Х	Х	Х	R	R	Steel or stainless steel serviceable in dry liquid or gas service
Hydrogen Chloride	\$		\diamond		Ν	Х		Х	Х	Х	R	R	Steel or stainless steel serviceable in dry liquid or gas service
Hydrogen Fluoride*	♦		\$		Х	R	R	R	R		R	R	Exposure can attack skin, bones and fingernails
Hydrogen Selenide	\$	♦			Ν	Ν	N	Х	R		R	R	Extremely toxic, odor deadens the olfactory nerves
Hydrogen Sulfide*	\$	♦			Ν	Ν	Ν	Х	R		R	R	Odor deadens olfactory nerves, can cause paralysis
Isobutane		♦			R	R	R	R	R		R	R	
lsobutylene		♦			R	R	R	R	R		R	R	
Krypton					R	R	R	R	R		R	R	

*It is recommended that users thoroughly familiarize themselves with the specific properties of this gas.

Middlesex Gases & Technologies, Inc. 292 Second Street PO Box 490249 Everett, MA 02149

(800) 649-6704 or (617) 387-5050 www.MiddlesexGases.com Info@MiddlesexGases.com

LEGEND

- ◊ Primary Hazard
- R Recommended

N - Not Recommended

X - Depends on conditions



GAS SAFETY AND MATERIAL COMPATIBILITY DATA CHART

H			М	ATER	IALS ()F COI	NSTRI	JCTION				
		mable	sive		inum	at /			1855		®	<u></u> ®
TOP	N 4185	in con		Alur	in Col	BIS	57 6388	stai	II. MOL	e ter	181	SPECIAL CHARACTERISTICS
	_				п	n	Р	Б		п		SPECIAL CHARACTERISTICS
V												
-												
-												Forms explosive compounds with aluminum
♦	♦			R	Ν	Х	R	R		R	R	
♦	0			Х	Ν	Ν	R	R		Х	R	Attacks copper and copper alloys rapidly
\diamond	\diamond			Х	Ν	Ν	R	R		Х	R	Attacks copper and copper alloys rapidly
				R	R	R	R	R		R	R	
\diamond		\diamond		R	Ν	Ν	Х	R	Ν	R	R	Readily reacts with Oxygen to form Nitrogen Dioxide
				R	R	R	R	R		R	R	
\diamond		\diamond		Ν	Ν	Ν	Ν	Ν	R		R	Very corrosive, attacks most metals except nickel
				R	R	R	R	R		R	R	
				R	R	R	R	R		R	R	Strong oxidant, ignites combustible matter spontaneously
♦		\diamond		Ν	Ν	Ν	Х	Х	R	R	R	Very toxic
♦	0			R	Х	Х	R	R		R	R	Highly toxic, high concentrations are pyrophoric
	♦			R	R	R	R	R		R	R	
	0			R	R	R	R	R		R	R	
♦	♦			R	R	R	R	R		R	R	Pyrophoric
0		\diamond										
0		0										
-												
0		0										
	0	v										Attacks copper and copper alloys rapidly
												התמטהס כטאושר מווע כטאושר מווטאס ומאועוא
					$ \begin{vmatrix} \circ & \circ & & & \\ & \circ & & & \\ & \circ & \circ & & \\ & \circ & \circ$	$ \sqrt{0}^{16} +u fitter Correstee Futurities 0 0 R R R R R 0 0 R R R N 0 0 X R N X 0 0 X R N X 0 0 X R N X 0 0 X R N X 0 0 X R R N 0 0 X R R R 0 0 X R R R 0 0 X R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R 0 0 R R R R $	\sqrt{N}	1000000000000000000000000000000000000	1000000000000000000000000000000000000	1000000000000000000000000000000000000	1000000000000000000000000000000000000	NORMALIZE NORMALIZE

*It is recommended that users thoroughly familiarize themselves with the specific properties of this gas.

All data presented are considered accurate and reliable but supplier assumes no liability or responsibility of any kind.

Middlesex Gases & Technologies, Inc. 292 Second Street PO Box 490249 Everett, MA 02149

(800) 649-6704 or (617) 387-5050 www.MiddlesexGases.com Info@MiddlesexGases.com

LEGEND

◊ - Primary HazardR - Recommended

N - Not Recommended

X - Depends on conditions